ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	13	Mallasandra
Street ID	**Street Name**	**Significant Landmark**
I0283, W0091, I0254	NA, Om Shakthi Lyt 3rd Crs	Opposite Maheshwaramma temple
Segment No.	**Total Length (m)**	
13/C-I0283/S032415	43.05	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	43.05	77.514058	13.047740	77.514433	13.047614	I0254	I0254

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Pipe line Park maintenance in ward no.13 in Shettyhalli Sub Division	2500000	2020
Year	**Type of Work**	**Other Work Type**
2019 - 2020	Others	
Tender	**Work Details**	**Job No. / Work Code**
Tender		013-20-000004
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/13/2021-22	07/06/2021	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
22/02/2022	15/02/2023	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Kumar D.V		2184838.00
Phone No.	**E-Mail ID**	
9845187283		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Rudramuni RT
Date of Inspection	**Remarks**	
25/02/2022		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	CE DAS	03/03/2022	27/03/2022	APPROVED
EE	EE DAS	03/03/2022	27/03/2022	FORWARDED
AEE	Janardhan	03/03/2022	27/03/2022	forwarded
AE	Rudramuni RT	25/02/2022	27/03/2022	forwarded
AE	Rudramuni RT	25/02/2022	27/03/2022	created

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** I0283, W0091, I0254